

ARIZONA HAZARDOUS WASTE MANIFEST

MANIFEST # 0264

Print or type all information on this form

SFUND RECORDS CTR
0222-90618I. PRODUCER OF WASTE (Must be filled out by Producer)NAME Shell Oil Co.PICK UP ADDRESS 109 N 55th Ave Phoenix 85063
Number Street City ZipTELEPHONE NO. 202-2631 ADHS Facility # N/A
(if applicable)TYPE OF PROCESS STORAGE TANK SLUDGEWHICH PRODUCED WASTE DIESEL SIC # 2911

DESCRIPTION OF WASTE (must be filled out by Producer)

Check type of waste:

- | | |
|--|---|
| <input type="checkbox"/> 1. acid solution | <input checked="" type="checkbox"/> 8. tank bottom sediment |
| <input type="checkbox"/> 2. alkaline solution | <input type="checkbox"/> 9. oil |
| <input type="checkbox"/> 3. pesticides | <input type="checkbox"/> 10. drilling mud |
| <input type="checkbox"/> 4. paint sludge | <input type="checkbox"/> 11. contaminated soil & sand |
| <input type="checkbox"/> 5. solvent | <input type="checkbox"/> 12. cannery wastes |
| <input type="checkbox"/> 6. tetraethyl lead sludge | <input type="checkbox"/> 13. latex waste |
| <input type="checkbox"/> 7. chemical toilet waste | <input type="checkbox"/> 14. mud and water |
| | <input type="checkbox"/> 15. brine |

Other (specify) _____

COMPONENTS:

CONCENTRATION

(Examples: Hydrochloric acid,
lime, caustic soda solvents
(lists), metals (lists)).

	upper	lower	%	ppm
1. <u>WATER</u>			<u>85</u>	<u>t</u>
2. <u>SAND</u>			<u>5</u>	
3. <u>RUST (FE2O3)</u>			<u>5</u>	
4. <u>H-C (C10 to C16)</u>			<u>5</u>	
5. _____				
6. _____				

HAZARDOUS PROPERTIES OF WASTE:

pH None Toxic Flammable corrosive explosiveBulk volume gal. 2000 tons barrels other (specify)
(42 gal)Containers drums cartons bags other Bulk
(number) (specify)Physical State: solid liquid sludge other (specify)

SPECIAL HANDLING INSTRUCTIONS (If any) _____

I certify that the above waste is accurately described.

8000066

DATE 10-9-79SIGNATURE R E Currell

I. ADHS APPROVAL

DISPOSAL AT: (Site) Missionary
(Area of site) Pit #1
APPROVED BY: Mark X Monos
DATE: 9 October 79
ARIZONA DEPARTMENT OF HEALTH SERVICES

I. HAULER OF WASTE (Must be filled out by Hauler)

NAME Arizona Landfill Corp.
BUSINESS ADDRESS 125 N. 55th Ave Phoenix AZ 85043
Number Street City Zip
TELEPHONE NO. 269-6106 PICK UP 10/8/79 TIME am 3 pm
JOB NO. Shall NO. OF LOADS/TRIPS (Date) 1 VEHICLE LIC. # 25J-611
VEHICLE: Vacuum Truck X Flatbed Other _____
(specify)

The described waste was hauled by me to the disposal facility named below and was accepted.

I CERTIFY THAT THE FOREGOING IS TRUE AND CORRECT

Mark X Monos
Signature of authorized agent and title

II. HAZARDOUS WASTE FACILITY (Must be filled in by Facility)

SITE ADDRESS MISSIONARY LANDFILL #7 ADHS PERMIT NO. N/A
QUANTITY MEASURED AT SITE (If applicable) _____

The above-named hauler delivered the described waste to this facility and was accepted this date.

Robert F. Hart
Signature of authorized agent and title

10-10-79
Date

ADDITIONAL COMMENTS:

ARIZONA HAZARDOUS WASTE MANIFEST

MANIFEST # 0.265

Print or type all information on this form

I. PRODUCER OF WASTE (Must be filled out by Producer)NAME Shell Oil Co.PICK UP ADDRESS 109 N. 55th Ave. Phoenix 85063
Number Street City ZipTELEPHONE NO. 272-2631 ADHS Facility # N/A
(if applicable)TYPE OF PROCESS STORAGE TANK SLUDGEWHICH PRODUCED WASTE dieselSIC # 2911

DESCRIPTION OF WASTE (must be filled out by Producer)

Check type of waste:

- | | |
|--|---|
| <input type="checkbox"/> 1. acid solution | <input checked="" type="checkbox"/> 8. tank bottom sediment |
| <input type="checkbox"/> 2. alkaline solution | <input type="checkbox"/> 9. oil |
| <input type="checkbox"/> 3. pesticides | <input type="checkbox"/> 10. drilling mud |
| <input type="checkbox"/> 4. paint sludge | <input type="checkbox"/> 11. contaminated soil & sand |
| <input type="checkbox"/> 5. solvent | <input type="checkbox"/> 12. cannery wastes |
| <input type="checkbox"/> 6. tetraethyl lead sludge | <input type="checkbox"/> 13. latex waste |
| <input type="checkbox"/> 7. chemical toilet waste | <input type="checkbox"/> 14. mud and water |
| | <input type="checkbox"/> 15. brine |

Other (specify) _____

COMPONENTS:

(Examples: Hydrochloric acid,
lime, caustic soda solvents
(lists), metals (lists)).

CONCENTRATION

	upper	lower	%	ppm
1. <u>WATER</u>			<u>85⁺</u>	
2. <u>SAND</u>			<u>5</u>	
3. <u>RUST (FE₂O₃)</u>			<u>5</u>	
4. <u>H-C. (C10 to C16)</u>			<u>5</u>	
5. _____				
6. _____				

HAZARDOUS PROPERTIES OF WASTE: NONE (NOT HAZARDOUS BY USPL DEFINITION)pH None Toxic None Flammable None corrosive None explosive NoneBulk volume ✓ gal. 2000 tons barrels None other None
(42 gal) (specify)Containers None drums None cartons None bags None other BULK
(number) (specify)Physical State: solid None liquid None sludge ✓ other None
(specify)

SPECIAL HANDLING INSTRUCTIONS (If any) _____

I certify that the above waste is accurately described.

DATE 10-9-79

SIGNATURE

R E Carroll

8000067

TITLE Director

MANIFEST # 02165

-2-

Bureau of Sanitation
411 No. 24th Street Phoenix
Telephone Number 255-1160

I. ADHS APPROVAL

DISPOSAL AT: (Site) Massaryama

(Area of site) Pit #1

APPROVED BY: Mark Thomas

ARIZONA DEPARTMENT OF HEALTH SERVICES

DATE: 9 October 79

II. HAULER OF WASTE (Must be filled out by Hauler)

NAME Ar. Bickum Contr.

BUSINESS ADDRESS

125
Number

N

55th
Street

PHOENIX

Ar
City

85043
Zip

TELEPHONE NO. 269-6106

PICK UP

10/11/79
(Date)

TIME

am

12
noon

JOB NO. Skell

NO. OF LOADS/TRIPS

2

VEHICLE LIC. # 255-611

VEHICLE: Vacuum Truck X

Flatbed

Other

(specify)

The described waste was hauled by me to the disposal facility named below and was accepted.

I CERTIFY THAT THE FOREGOING IS TRUE AND CORRECT

Mark Thomas
Signature of authorized agent and title

IV. HAZARDOUS WASTE FACILITY (Must be filled in by Facility)

SITE ADDRESS

MASSARYAMA LANDFILL #7

ADHS PERMIT NO. N/A

QUANTITY MEASURED AT SITE (If applicable)

The above-named hauler delivered the described waste to this facility and was accepted this date.

Richard F. Light
Signature of authorized agent and title

10-11-79
Date

ADDITIONAL COMMENTS:

ARIZONA HAZARDOUS WASTE MANIFEST

MANIFEST # 0266

Print or type all information on this form

VOID

I. PRODUCER OF WASTE (Must be filled out by Producer)

NAME SHELL OIL CO.PICK UP ADDRESS 109 N. 55th Ave. Phoenix 85063
Number Street City ZipTELEPHONE NO. 282-2631 ADHS Facility # N/A
(if applicable)TYPE OF PROCESS STORAGE TANK SLUDGE
WHICH PRODUCED WASTE DIESEL SIC # 2911

DESCRIPTION OF WASTE (must be filled out by Producer)

Check type of waste:

- | | |
|--|---|
| <input type="checkbox"/> 1. acid solution | <input checked="" type="checkbox"/> 8. tank bottom sediment |
| <input type="checkbox"/> 2. alkaline solution | <input type="checkbox"/> 9. oil |
| <input type="checkbox"/> 3. pesticides | <input type="checkbox"/> 10. drilling mud |
| <input type="checkbox"/> 4. paint sludge | <input type="checkbox"/> 11. contaminated soil & sand |
| <input type="checkbox"/> 5. solvent | <input type="checkbox"/> 12. cannery wastes |
| <input type="checkbox"/> 6. tetraethyl lead sludge | <input type="checkbox"/> 13. latex waste |
| <input type="checkbox"/> 7. chemical toilet waste | <input type="checkbox"/> 14. mud and water |
| | <input type="checkbox"/> 15. brine |

Other (specify) _____

COMPONENTS:

(Examples: Hydrochloric acid, lime, caustic soda solvents (lists), metals (lists)).

CONCENTRATION

	upper	lower	%	ppm
1. <u>WATER</u>			<u>85 ±</u>	
2. <u>SAND</u>			<u>5</u>	
3. <u>RUST (FE2 O3)</u>			<u>5</u>	
4. <u>H.C. (C10 & C16)</u>			<u>5</u>	
5.				
6.				

HAZARDOUS PROPERTIES OF WASTE: NO.VE (NOT HAZARDOUS BY USDL DEFINITION)pH None Toxic Flammable corrosive explosiveBulk volume ✓ gal. tons barrels other (specify)
(42 gal)Containers drums cartons bags other BULK
(number) (specify)Physical State: solid liquid sludge ✓ other (specify)

SPECIAL HANDLING INSTRUCTIONS (If any) _____

I certify that the above waste is accurately described.

DATE 10-9-79 SIGNATURE R E CaroselliTITLE Plant Subst.

8000068

MANIFEST # 0266

-2-

DEPARTMENT OF HEALTH SERVICES
Bureau of Sanitation
411 No. 24th Street Phoenix
Telephone Number 255-1160

II. ADHS APPROVAL

DISPOSAL AT: (Site) Hasseyampa
(Area of site) Pit #1

APPROVED BY: [Signature]

ARIZONA DEPARTMENT OF HEALTH SERVICES

DATE: 9 October 79

III. HAULER OF WASTE (Must be filled out by Hauler)

NAME _____

BUSINESS ADDRESS _____

Number Street City Zip

TELEPHONE NO. _____ PICK UP _____ TIME _____ am _____ pm

JOB NO. _____ NO. OF LOADS/TRIPS (Date) _____ VEHICLE LIC. # _____

VEHICLE: Vacuum Truck _____ Flatbed _____ Other _____
(specify)

The described waste was hauled by me to the disposal facility named below and was accepted.

I CERTIFY THAT THE FOREGOING IS TRUE AND CORRECT

Signature of authorized agent and title

IV. HAZARDOUS WASTE FACILITY (Must be filled in by Facility)

SITE ADDRESS _____ ADHS PERMIT NO. N/A

QUANTITY MEASURED AT SITE (If applicable) _____

The above-named hauler delivered the described waste to this facility and was accepted this date.

Signature of authorized agent and title

Date

ADDITIONAL COMMENTS: Known to Void

Hauled under manifest #0264 - this manifest not needed
in completion of contract

ARIZONA HAZARDOUS WASTE MANIFEST

MANIFEST # 0267

Print or type all information on this form

VOID

I. PRODUCER OF WASTE (Must be filled out by Producer)

NAME Shell Oil Co.PICK UP ADDRESS 109 N. 55th Ave Phoc 85063
Number Street City ZipTELEPHONE NO. 202-2631 ADHS Facility # N/A
(if applicable)TYPE OF PROCESS STORAGE TANK SLUDGEWHICH PRODUCED WASTE diesel SIC # 2911

DESCRIPTION OF WASTE (must be filled out by Producer)

Check type of waste:

- | | |
|--|---|
| <input type="checkbox"/> 1. acid solution | <input checked="" type="checkbox"/> 8. tank bottom sediment |
| <input type="checkbox"/> 2. alkaline solution | <input type="checkbox"/> 9. oil |
| <input type="checkbox"/> 3. pesticides | <input type="checkbox"/> 10. drilling mud |
| <input type="checkbox"/> 4. paint sludge | <input type="checkbox"/> 11. contaminated soil & sand |
| <input type="checkbox"/> 5. solvent | <input type="checkbox"/> 12. cannery wastes |
| <input type="checkbox"/> 6. tetraethyl lead sludge | <input type="checkbox"/> 13. latex waste |
| <input type="checkbox"/> 7. chemical toilet waste | <input type="checkbox"/> 14. mud and water |
| | <input type="checkbox"/> 15. brine |

Other (specify) _____

COMPONENTS:

(Examples: Hydrochloric acid, lime, caustic soda solvents (lists), metals (lists)).

CONCENTRATION

	upper	lower	%	ppm
1. <u>WATER</u>			<u>85⁺</u>	
2. <u>SAND</u>			<u>5</u>	
3. <u>RUST (Fe₂O₃)</u>			<u>5</u>	
4. <u>H-C. (C10 to C16)</u>			<u>5</u>	
5. _____				
6. _____				

HAZARDOUS PROPERTIES OF WASTE: PER USDOT DEF.

pH None ☒ Toxic ☐ Flammable ☐ corrosive ☐ explosive
Bulk volume ☒ gal. ☐ tons ☐ barrels ☐ other ☐
(42 gal) (specify)Containers ☐ drums ☐ cartons ☐ bags ☐ other BULK
(number) (specify)Physical State: solid ☐ liquid ☐ sludge ☒ other ☐
(specify)

SPECIAL HANDLING INSTRUCTIONS (If any) _____

I certify that the above waste is accurately described.

8000069

DATE 10-9-79 SIGNATURE R E CarozellTITLE Plant Subst

MANIFEST # 0267

-2-

DEPARTMENT OF HEALTH SERVICES
Bureau of Sanitation
411 No. 24th Street Phoenix
Telephone Number 255-1160

II. ADHS APPROVAL

DISPOSAL AT: (Site) Hassayampa
(Area of site) Pit #1
APPROVED BY: Shirley Mapes
DATE: 9 October 79
ARIZONA DEPARTMENT OF HEALTH SERVICES

III. HAULER OF WASTE (Must be filled out by Hauler)

NAME _____
BUSINESS ADDRESS _____
Number Street City Zip
TELEPHONE NO. _____ PICK UP _____ TIME _____ am _____ pm
JOB NO. _____ NO. OF LOADS/TRIPS (Date) _____ VEHICLE LIC. # _____
VEHICLE: Vacuum Truck _____ Flatbed _____ Other _____ (specify)

The described waste was hauled by me to the disposal facility named below and was accepted.

I CERTIFY THAT THE FOREGOING IS TRUE AND CORRECT

Signature of authorized agent and title

IV. HAZARDOUS WASTE FACILITY (Must be filled in by Facility)

SITE ADDRESS _____ ADHS PERMIT NO. N/A
QUANTITY MEASURED AT SITE (If applicable) _____

The above-named hauler delivered the described waste to this facility and was accepted this date.

Signature of authorized agent and title

Date

ADDITIONAL COMMENTS: Reason for void

Hauled under manifest #0265 - this manifest not needed for completion of contract